



# Shield Care Instructions

## INSTRUCTIONS

---



### **Wash and Rinse**

Use a neutral detergent diluted with water to gently wash your helmet shield. Rinse thoroughly with clean water to remove any soap residue.



### **Drying**

After washing, wipe off excess moisture with a soft cloth. Allow the shield to dry naturally in a well-ventilated area.

## IMPORTANT PRECAUTIONS

---



### **Avoid Harsh Cleaners**

Do not use cleaners containing organic solvents, such as hot water, salt water, acidic or alkaline detergents, benzene, thinner, gasoline, or glass cleaner, especially if the temperature exceeds 40°C.



### **No Heat Drying**

Do not use a dryer or expose the shield to direct fire to dry.



### **Replacement**

If your shield has scratches or stains that cannot be removed, consider replacing it with a new one for optimal visibility and safety.

